- o Do not resume printer use until the printer has been put back into service.

If a 3D printer user shows signs of chemical exposure or other injury/illness:

symptoms may include dizziness, headache, faint/lightheaded feeling, confusion, slurred speech, etc.
  - o Stop printer use and immediately notify the faculty member, technician, or monitor on duty, who will call RWU Public Safety at **401-254-3333**.
  - o Provide a copy of the product SDS to RWU Public Safety and/or other responding emergency personnel

If a 3D printer product ignites, begins to smoke, or otherwise catch fire:
  - o Immediately stop the printer and notify the faculty member, technician, or monitor on duty
  - o Evacuate the building following emergency evacuation procedures
  - o From a safe place, call RWU Public Safety at **401-254-3333**.

3D Printer Training Requirements

All 3D printer users must complete the following safety training requirements:

Have a current Shop and Studio Safety Agreement on file

Have current completions for all relevant general safety training for the work area, as listed on the RWU Laboratory, Shop, and Studio Safety Training Requirements Links for the current academic year

Have current completion for the 3D Printer Training on the RWU Laboratory, Shop, and Studio Safety Training Requirements Links for the current academic year

Have completed a documented hands-on 3D printer training session with an approved faculty member, technician, or monitor for the current academic year